WELL SUMMARY

Location ID: <u>NASA-8</u>

Pertinent Field Notes:

03/24/89	Lockheed removes dedicated bladder pump. Larjon adds 5' of PVC and 5' of protective steel casing to top of well in preparation for closure of 600 Area Impoundment Kaszuba
07/89	New concrete pad installed by Lockheed because old pad was covered during closure activities. Larjon cut inner PVC casing addition from 03/24/89 down to 3.0' above new concrete pad Egan
08/04/89	Updated survey data on well submitted to GCL by Botsford Land Surveying, Inc. Data is included in well file Egan
10/17/89	Redevelop well due to turbidity problems. Install poly-pipe in screen and jet with compressed air (filtered) Egan See redevelopment sheet for details.
10/20/89	Stop redevelopment at NASA-8 due to needs for this equipment on higher priority monitor well installations. Redevelopment of NASA-8 put on hold until equipment is available Egan
01/09/90	Lockheed Environmental Group has purchased equipment to conduct their own redevelopment of monitor wells and will redevelop NASA-8 Egan